

SUMMARY OF CHINO BASIN GROUNDWATER RECHARGE OPERATIONS					
February 2015					
Drainage System	Recharge Volume (AF)*			Management	
Basin	SW/LR	MW	RW	Zone Subtotals	
San Antonio Channel Drainage System					
College Heights	-	-	N	MZ-1 202 AF**	
Upland	29	-	N		
Montclair 1, 2, 3 & 4	30	-	N		
Brooks	27	-	92		
West Cucamonga Channel Drainage System					
8th Street	37	-	-	MZ-2 974 AF**	
7th Street	5	-	-		
Ely 1, 2, & 3	72	-	222		
Minor Drainage					
Grove	29	N	N		
Cucamonga and Deer Creek Channel Drainage Systems					
Turner 1 & 2	93	-	60		
Turner 3 & 4	65	-	53		
Day Creek Channel Drainage System					
Lower Day	17	-	X		
Etiwanda Channel Drainage System					
Etiwanda Debris	-	-	X		
Victoria	40	-	57		
San Sevaine Channel Drainage System					
San Sevaine 1, 2, 3, & 4	8	-	-		
San Sevaine 5	31	-	-		
West Fontana Channel System					
Hickory	47	-	180		
Banana	16	-	47		
Declez Channel Drainage System					
RP3 Cells 1, 3, & 4	74	-	243		
RP3 Cell 2	21	-	-		
Declez	106	-	-		
Non-Replenishment Recharge**					
Brooks (MVWD) MZ-1	(7)				
Montclair (MVWD) MZ-1	(11)				
Turner (CVWD) MZ-2	-				
Month Total = 1,683 AF					
	729	0	954	February 2015	
Fiscal Year to Date Total					
Since July 1, 2014 = 12,998 AF	6,640	0	6,358	Fiscal Year to Date	
Calendar Year to Date Total					
Since Jan. 1, 2015 = 2,982 AF	1,405	0	1,577	Calendar Year to Date	
SW : Storm Water, LR : Local Runoff (and GE, MVWD), MW : MWD Imported Water, RW : Recycled Water					
- : No stormwater/local runoff, or basin not in use due to maintenance or testing.					
X : Turnouts not available - to be installed during future projects.					
N : No turnout planned for installation.					
* : Data are preliminary based on the data available at the time of this report preparation.					
** : Management Zone Subtotals have deducted from them any Non-Replenishment Recharge, which is recharge originating from pumped groundwater and is not new water.					