SUMMARY OF CHINO BASIN GROUNDWATER RECHARGE OPERATIONS				
September 2015				
Drainage System	Recharge Volume (AF)*		Management	
Basin	SW/LR	MW	RW	Zone Subtotals
San Antonio Channel Drainage System				
College Heights	-	-	N	MZ-1
Upland	29	-	N	206
Montclair 1, 2, 3 & 4	42	-	N	AF**
Brooks	-	-	-	
West Cucamonga Channel Drainage System				
8th Street	19	-	-	
7th Street	57	-	60	
Ely 1, 2, & 3	215	-	31	
Minor Drainage				
Grove	82	N	N	
Cucamonga and Deer Creek Channel Drainage	Systems		•	
Turner 1 & 2	120	-	145	
Turner 3 & 4	74	-	51	MZ-2
Day Creek Channel Drainage System				1,092
Lower Day	19	-	X	ÁF**
Etiwanda Channel Drainage System			<u> </u>	
Etiwanda Debris	13	-	X	
Victoria	37	=	136	
San Sevaine Channel Drainage System				
San Sevaine 1, 2, 3, & 4	28	-	-	
San Sevaine 5	25	-	_	-
West Fontana Channel System				
Hickory	9	-	107	
Banana	40	-	376	
Declez Channel Drainage System				MZ-3
RP3 Cells 1,3, & 4	75	-	219	905
RP3 Cell 2	48	-	-	AF**
Declez	147	_	_	7 11
Non-Replenishment Recharge**	147		<u> </u>	
Brooks (MVWD) MZ-1				
Montclair (MVWD) MZ-1	(1)			
Turner (CVWD) MZ-2	-			
Month Total = 2,203 AF	1,078	-	1,125	September 2015
Fiscal Year to Date Total				Fiscal Year
Since July 1, $2015 = 4,439 \text{ AF}$	1,859	-	2,580	to Date
Calendar Year to Date Total	,		ĺ	Calendar Year
Since Jan. 1, $2015 = 13,259 \text{ AF}$	4,620	0.0	8,639	to Date

SW: Storm Water, LR: Local Runoff (and GE, MVWD), MW: MWD Imported Water, RW: Recycled Water

N : No turnout planned for installation.

Printed: Feb. 02, 16

^{- :} No stormwater/local runoff, or basin not in use due to maintenance or testing.

X : Turnouts not available - to be installed during future projects.

^{* :} Data are preliminary based on the data available at the time of this report preparation.

^{** :} Management Zone Subtotals have deducted from them any Non-Replenishment Recharge, which is recharge originating from pumped groundwater and is not new water.